



**Hyundai Motor America**  
10500 Talbert Avenue, Fountain Valley, CA 92708  
TEL: 714-965-3000 FAX: 714-965-3816  
WEB: Hyundai.com

March 28, 2018

**TO: Collision Repair Industry**

**POSITION STATEMENT: Aluminum and Steel Wheel Repair & Reconditioning**

Hyundai Motor America does not approve the use of reconditioned steel or aluminum wheels on any Hyundai vehicle. Reconditioned wheels may not meet the same standards as newly manufactured wheels. Reconditioned wheels may contribute to poor performance and compromise safety.

Post collision wheel inspection must be performed on all wheels with special attention to wheel(s) subject to the impact zone.

Hyundai only recognizes steel or aluminum wheel repair that is limited to surface treatment that restores cosmetic appearance of the finish coating.